


















QUICK GUIDE

(IT) GUIDA RAPIDA	(PT) MANUAL RÁPIDO	(CS) RYCHLÁ PŘÍRUČKA	(NO) HURTIG GUIDE	(ET) KIIRJUHENDIT
(FR) GUIDE RAPIDE	(NL) SNELGIDS	(HR-SR) BRZI VODIČ	(SL) HITER VODIČ	(LV) ĀTRĀ PAMĀCĪBA
(ES) GUÍA RÁPIDA	(EL) ΣΥΝΤΟΜΟΣ ΟΔΗΓΟΣ	(PL) SKRÓCONA INSTRUKCJA	(SK) RÝCHLA PŘÍRUČKA	(BG) КРАТКО РЪКОВОДСТВО
(DE) KURZANLEITUNG	(RO) GHIDUL RAPID	(FI) PIKAOPAS	(HU) GYORS ÚTMUTATÓ	(TR) HIZLI REHBER
(RU) КРАТКОЕ РУКОВОДСТВО	(SV) SNABBGUIDE	(DA) LYNVEJLEDNINGEN	(LT) GREITAS VADOVAS	(AR) سريع الخطر

INDEX

 WELDING 1 - 13	 BATTERY RECHARGE 14 - 17	 BATTERY CARE 2 / 18
 1	 2	 3
 4	 5	 6
 7	 8	 9
 10		



WE CARE ABOUT
THE ENVIROMENT
FIND THE MANUAL ONLINE



